

Release Notes 93000221W  
for  
PORTSERVER II Operating System  
40001260V  
Version 3.1.2  
Software Manual P/N 92000246B  
Software Manual P/N 92000271A  
February 22, 2001

## I. Introduction

These release notes provide information on PortServer II OS version 3.1.2.

## II. Summary

- A. Pre-3.0 Incompatibility Notice
- B. Pre-Rev K Model ROM Limitations
- C. Limitations for Systems with 2 Mb of Memory
- D. Upgrading flash ROM.

## III. Details

### A. Pre-3.0 Incompatibility Notice

This version (3.1.2) of the PortServer II OS is incompatible with versions older than 3.0. Certain parts of the non-volatile storage formats used to store configuration information have been changed. Consequently, if you want to use this version of the OS and preserve your current configuration, you must use the `cpconf` command to save your configuration to a host and then restore it once the new version of the PortServer II OS has been installed.

### B. Pre-Rev K Model ROM Limitations\*

The addition of Frame Relay to 3.0 and later versions of the OS causes the size of the boot image to exceed the space available in the PortServer II flash ROM for units built prior to the Rev K models. Consequently, if you want to use a 3.0 or later OS with these older units, you must do one of the following:

- Boot PortServer II via TFTP over the ethernet port.
- Acquire a smaller version of the OS, which does not have Frame Relay, this is available from the Digi ftp site.

\*NOTE: Versions above and including 3.1.0 will no longer be available in the smaller non-frame version.

### C. Limitations for Systems with 2 Mb of Memory

Testing has determined that the PortServer II's previously standard 2 Mb of installed memory is inadequate in the following instances and is likely to require an expansion to at least 4 Mb.

- Full 64 port configurations in which more than 50 asynchronous and/or TCP users are simultaneously using PortServer II. This includes users accessing the PortServer II via the ethernet connection or any type of connection using the serial ports.

Note: Exceeding this number of users is unlikely in RealPort environments because each RealPort connection is seen as a single user. This means that while that user may control more than one port, if there is only one host connected to the PortServer II using RealPort, it will use only a little more memory than someone making a telnet connection. If more than one host is using PortServer II as a RealPort server, each host will have it's own TCP connection, and

therefore each is considered a user. It is unlikely that a site will have enough RealPort connections to cause problems.

- Sites with heavy traffic on serial ports. Here the problem is simply throughput. Degradation of performance may indicate that additional memory is called for.

#### D. Upgrading Flash ROM

Should it be necessary to update the PortServer II OS contained in Flash ROM on your PortServer II, the recommended procedure is:

1. Obtain the new version of the software from Digi and place it on your TFTP server.
2. Save your current configuration using `cpconf`. This should not be necessary, but it is advisable to maintain a backup of your current configuration when re-writing a sizable portion of flash.
3. Boot your PortServer II with the new operating system via TFTP, by using `set config boothost=hostip bootfile=filename tftpboot=yes`, and then rebooting your PortServer II. See command `set config` in User's Guide and Reference Manual for more details. This step ensures that you have a good copy of the new version of the software, and also that you can still boot your PortServer II in the unlikely event that your flash image gets corrupted in the process of writing it.
4. After booting your PortServer II via TFTP, load the new version of the software into the flash ROM by using the command `boot load=host:filename`. If all goes well, the PortServer II will reply "The image now in flash memory appears valid."
5. Now you can return your PortServer II to booting from its flash ROM image by entering the command `set config tftpboot=no`.

\*NOTE – In some instances parameters from 3.0.13 may not translate properly into 3.1.2. In order to insure that the parameters are correct the user can save their parameters from 3.0.13 by doing a `cpconf` and reloading the parameters back into the PortServer II after 3.1.2 is loaded.