



PRODUCT NOTICE # 101217

Date:

December 17, 2010

Product:

XBee-PRO 900 Firmware Update

Affected Part Numbers:

Part Number	Description	New Revision
XBP09-DPSIT-156	XBee PRO 900 RPSMA	C
XBP09-DPUIT-156	XBee PRO 900 U.FL	C
XBP09-DPWIT-156	XBee PRO 900 Wire	C
XBP09-DPSIT-501	XBee PRO 900 RPSMA 232	B
XA-X91-CS2P-AH	XBee, 900 MHz Adapter RS232 9-30VDC	B

Notice:

On December 17, 2010 the XBee-PRO 900 module production firmware was changed from 1002 to 1061. New revisions will be in stock and begin shipping on January 31, 2011.

Details:

This update added asynchronous sleep modes, fixed a bug where the pull-up on DIN was not getting properly set, and fixed a bug where no response was received for a failed RMT AT CMD request transmission.

Additional Information:

For customers who wish to test the new 1061 firmware, it is available now for download by using X-CTU > Modem Configuration tab > Download new versions ... button > Web.

More details can be found on our Support site at

<http://www.digi.com/support/productdetl.jsp?pid=3421&osvid=0&s=364&tp=2>, including:

- Firmware revision history
- Firmware download
- Instructions for downloading and installing new firmware

See page 2 of this PCN for a sample XBee label and how to find the Revision and other relevant information.



If you have concerns or questions about this notice please contact our support department via telephone at 801-765-9885 or visit us online at <http://www.digi.com/support/eservice/> to submit a request.

Product Management
Digi International