



## PRODUCT NOTICE # 101129

**Date:**

November 29, 2010

**Product:**

XBee-PRO XSC Firmware Update

**Affected Part Numbers:**

Part Number	Description	New Revision
XBP09-XCUIT-009	XBee PRO XSC 900MHz 9600bps U.fl	B
XBP09-XCSIT-009	XBee PRO XSC 900MHz 9600bps SMA	B
XBP09-XCWIT-009	XBee PRO XSC 900MHz 9600bps WIRE	B
XBP09-XC009-DK	XBee-PRO XSC009 Dev Kit	D

**Notice:**

On November 29, 2010 the XBee-PRO XSC module production firmware was changed from 1020 to 1022. New revisions will be in stock and begin shipping on January 15, 2011.

**Details:**

This update fixed a flow control bug that caused the module to lock up if RTS was held high for too long. This bug only occurred when the UART had data in its buffer.

**Additional Information:**

For customers who wish to test the new 1022 firmware, it is available now for download by using X-CTU > Modem Configuration tab > Download new versions ... button > Web.

More details can be found on our Support site at

<http://www.digi.com/support/productdetl.jsp?pid=3421&osvid=0&s=364&tp=2>, including:

- Firmware revision history
- Firmware download
- Instructions for downloading and installing new firmware

See page 2 of this PCN for a sample XBee label and how to find the Revision and other relevant information.



If you have concerns or questions about this notice please contact our support department via telephone at 801-765-9885 or visit us online at <http://www.digi.com/support/eservice/> to submit a request.

---

Product Management  
Digi International