# Hardware Installation Guide
NET+50

Complete the Hardware Installation Guide first,
then go to the Getting Started Guide for software installation

1 Unpack the contents of the Net+50 and verify all the components

top view

Software CD

Documentation

Power supply for debugger

JTAG

Development board

Raven debugger

Crossover serial cable

RJ-45 cable

Power supply for board

2 Connect the Raven debugger

Pin 1

Raven   Connect Raven to PC parallel port

Connect ribbon cable from Raven to JTAG header on development board

Connect power supply to Raven debugger and to power source

3 Connect development board

Connect the power supply to the NET+50 development board and the power source

Connect crossover cable between serial port A on development board and available COM port on PC

Connect Ethernet cable to development board

WHAT'S NEXT?

The hardware installation is complete. The next step is to go to the Getting Started Guide to install your software.

visit us at www.digi.com

PN:(1P) 90000532   D