Release Notes (93001322)

Digi Connect IT 16/48

Version 19.3.8.59 - May 2019

INTRODUCTION

This is a production firmware release for the Digi Connect IT 16/48 for mass production.

SUPPORTED PRODUCTS

- Digi Connect IT 16
- Digi Connect IT 48

SUPPORTED WEB BROWSERS

The following web browsers are supported with the web interface. The latest version and the previous version of each browser have been tested.

- Google Chrome
- Firefox
- Microsoft Internet Explorer 11
- Microsoft Edge

KNOWN ISSUES

1. N/A

HISTORY

19.3.8.59 – May 2019

ENHANCEMENTS

- 1. Add find-me LED support (DAL-904)
- 2. quiet boot (no console output) (DAL-938)
- 3. Product name reformat (DAL-900)
- 4. Updated network port default configurations (DAL-932)
- 5. Support to direct remote serial port access via webui (DAL-775)

SECURITY BUG FIXES

1. N/A

BUG FIXES

- 1. restore last active SIM slot on boot
- 2. fixes for DRM metrics/health
- 3. Corrected WWAN LED status
- 4. Corrected port naming
- 5. Status LED updates (DAL-898, DAL-899)

- 6. PSU LED updates (DAL-898, DAL-899)
- 7. Increase allowable firmware upgrade size (DAL-931)

Earlier Releases

For the release notes for earlier firmware releases, please visit the Digi Support site (www.digi.com/support).