19.1.134.92 Firmware Release Notes

Targets: EX15, EX15W

Release date: 2019-03-09

The below are changes between firmware versions 19.1.134.81 and 19.1.134.92

- Fixed bug where the same MAC address would be assigned to both the WAN and WLAN0 interfaces
- Fixed bug where no LEDs are illuminated for the first 30 seconds after applying power
 - The LTE LED will illuminate solid yellow
- Updated 5G WiFi options to only list channels 36-48
- Removed 80MHz bandwidth option from WiFi settings
- Updated metrics posted to DRM to include the description field in the system group