

Install Software




Note: Microsoft Windows may indicate that the JTAG Link driver is not digitally signed. Please click "Continue Anyway" to complete the installation of the software.

Connect Wi-ME™
Connect ME™




Connect Hardware to Development Board

Tip:
You may defer connecting the hardware until you are ready to test your application.




Connect JTAG Adapter to Module



Orient tab on connector to tab printed on development board. JTAG link debugger ribbon is highlighted to line up with pin 1.



Connect USB JTAG Debugger to USB Port



Congratulations,
Your hardware installation is complete. Return to the Welcome screen from the software installation and click the Getting Started link.

IMPORTANT! You must install the software before connecting the Digi JTAG Link Debugger.

