



# Digi Connect WAN Hardware Change Notice

50000894-40 and higher

## **Increased Memory Size**

- The Digi Connect WAN hardware now contains 16MB of RAM and 8MB of flash memory to support new features including a Python® engine for development of custom applications.
- Updated firmware (v2.7.x or later) is required on all Digi Connect WAN products with increased memory.

## **Serial Port Configuration**

- All Connect WAN products support the selection of either RS232, RS422, or RS485 on the serial port.
- Default setting is RS232, 9600, 8/N/1.
- All serial port configuration parameters are now software selectable and do not require a mechanical Dip Switch.
- Use the 'set switches' command or check the User Guide for more details.

## **Improved SIM Card Socket**

- A new SIM Card socket for GSM models has been incorporated.
- This new socket has improved contacts between the SIM and the socket in addition to a push-to-eject feature.
- Note new orientation of SIM when inserting. Refer to product labeling for details.

## **Aux Port**

- The external Auxiliary / modem port has been removed from the product. This port was used for manufacturing of the product and was not accessible by customers.



(1P): 90000947-88 A